

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	272	(166/379).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/28 07:51
L2	206	(166/379).CCLS.	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/28 07:53
L3	0	(166/74.15).CCLS.	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/28 07:53
L4	132	(166/75.14).CCLS.	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/28 07:56
L5	172	(166/75.14).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/28 07:57
L6	116	(166/85.4).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/28 07:59
L7	0	(wellhead adapter nipple flange passage thread\$3).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2005/11/28 08:01
L8	0	(wellhead adapter nipple flange passage thread\$3).clm.	US-PGPUB	SAME	ON	2005/11/28 08:01
L9	0	(wellhead adapter nipple flange passage thread).clm.	US-PGPUB	SAME	ON	2005/11/28 08:01
L10	0	(adapter nipple flange passage thread).clm.	US-PGPUB	SAME	ON	2005/11/28 08:01
L11	0	(adapter nipple flange passage thread).clm.	US-PGPUB	AND	ON	2005/11/28 08:01
L12	24	(adapter flange passage thread).clm.	US-PGPUB	AND	ON	2005/11/28 08:01